IKM Testing AS

Unit No. DPM-19

DEW POINT INDICATOR

Dimension	:	W 430 mm	L 350 mm	H 105 mm
Weight	:	4 kg		

Operating range humidity	:	0…100%
Operating range temperature	:	-10…+60°C
Operating range dew point	:|	-60…+20°C
Pressure range	:	0…20 Bar (10 Bar max. for DSC74)
Battery	:	Chargeable NIMH-battery or 4 x LR6 alkaline battery

Type	:	Vaisala DM-70 Hand held dew point indicator
Ser. no.	:	E3830003
Contents	:	MI70 Display-unit, DMP74B sensor, DSC74 Pressure adapter, MI70 logging-software, pc-cable, fittings for pressure adapter and cable for Analogue output.
Equipment/Functions	:	DSC74 Pressure adapter 3/8", software and cable for PC-logging.
Built	:	2009