

PRESSURE / TORQUE CONVERSION CHART
XLCT SERIES WITH HEX DRIVES

Pressure in PSI	2XLCT	4XLCT	8XLCT	14XLCT	18XLCT	30XLCT
	Torque in Ft. Lbs					
1500	243	580	1143	2010	2676	4770
1600	259	618	1234	2144	2857	5088
1800	292	694	1417	2412	3211	5724
2000	325	770	1600	2680	3565	6360
2200	359	847	1754	2948	3928	6996
2400	392	924	1907	3216	4282	7632
2600	426	1001	2061	3484	4636	8268
2800	459	1078	2214	3752	4998	8904
3000	493	1155	2368	4020	5350	9540
3200	526	1232	2533	4288	5709	10176
3400	559	1309	2698	4556	6068	10812
3600	591	1386	2864	4824	6423	11448
3800	624	1463	3029	5092	6785	12084
4000	657	1540	3194	5360	7140	12720
4200	691	1618	3358	5628	7493	13356
4400	726	1696	3522	5896	7855	13992
4600	760	1774	3685	6164	8209	14628
4800	795	1852	3849	6432	8564	15264
5000	829	1930	4013	6700	8920	15900
5200	863	2007	4176	6968	9280	16536
5400	897	2084	4340	7236	9634	17172
5600	931	2161	4503	7504	9996	17808
5800	965	2238	4667	7772	10350	18444
6000	999	2315	4830	8040	10705	19080
6200	1033	2392	4996	8308	11066	19716
6400	1067	2469	5161	8576	11421	20352
6600	1102	2546	5327	8844	11775	20988
6800	1136	2623	5492	9112	12137	21624
7000	1170	2700	5658	9380	12490	22260
7200	1204	2777	5825	9648	12773	22896
7400	1239	2854	5992	9916	13207	23532
7600	1273	2931	6158	10184	13562	24168
7800	1308	3008	6325	10452	13916	24804
8000	1342	3085	6492	10720	14280	25440
8200	1377	3163	6658	10988	14632	26076
8400	1412	3241	6823	11256	14994	26712
8600	1446	3319	6989	11524	15348	27348
8800	1481	3397	7154	11792	15703	27984
9000	1516	3475	7320	12060	16065	28620
9200	1550	3551	7486	12328	16419	29256
9400	1584	3627	7652	12596	16773	29892
9600	1619	3703	7819	12864	17135	30528
9800	1653	3779	7985	13132	17489	31164
10000	1687	3855	8151	13400	17845	31800